



· At least 2 measurements per day on a test block in the hardness range of the material to be tested

· At least 2 measurements per day on a test block in the hardness range of the material to be tested

At least 2 measurements per day on a test block in the hardness range of the material to be tested and at least 2 pre-measurements that are discarded