



• At least 2 measurements per day on a test block in the hardness range of the material to be tested. • At least 2 measurements per day on a test block in the hardness range of the material to be tested.

## At least 2 measurements per day on a test block in the hardness range of the material to be tested and at least 2 pre-measurements that are discarded.